

Water Quality Database
Well Status Types

Code	Description
3	LOST WELL THAT COULD NOT BE LOCATED
4	EXTERNAL CONDITION PRECLUDED WATER LEVEL MEASUREMENT.
A	WELL WAS ABANDONED
B	WELL WAS BORED OUT FORMING A NEW WELL
C	WELL WAS CAPPED
D	SITE WAS DRY (NO WATER LEVEL IS RECORDED).
E	SITE WAS FLOWING RECENTLY
F	SITE WAS FLOWING, BUT THE HEAD COULD NOT BE MEASURED
G	NEARBY SITE THAT TAPS THE SAME AQUIFER WAS FLOWING
H	NEARBY SITE TAPPING SAME AQUIFER HAD BEEN FLOWING RECENTLY
I	INJECTOR SITE (RECHARGES WATER BEING INJECTED INTO AQUIFER
J	INJECTOR SITE MONITOR, NEARBY SITE TAPPING AQUIFER INJECTING
N	THE MEASUREMENT WAS DISCONTINUED
O	OBSTRUCTION WAS ENCOUNTERED IN WELL ABOVE WATER SURFACE
P	SITE WAS BEING PUMPED
R	SITE HAD BEEN PUMPED RECENTLY
S	NEARBY SITE THAT TAPS THE SAME AQUIFER WAS BEING PUMPED
T	NEARBY SITE TAPPING THE SAME AQUIFER WAS PUMPED RECENTLY
V	FOREIGN SUBSTANCE WAS PRESENT ON THE SURFACE OF THE WATER
W	WELL WAS DESTROYED
X	WATER LEVEL AFFECTED BY STAGE IN NEARBY SURFACE WATER SITE
Z	OTHER CONDITIONS THAT WOULD AFFECT THE MEASURED WATER LEVEL